



**Airforce Turbine Service**  
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368  
 P.O. Box 146 Tynan, TX 78391  
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

<b>Engine Rotor Sheet</b>							
PT6A:	<b>-34</b>	TSN:	<b>10,998.1</b>	TSO:	<b>3,302.0</b>	W/O#:	<b>10286</b>
PCE:	<b>50815</b>	CSN:	<b>16,840</b>	CSO:	<b>4,411</b>	TSHS:	<b>0.0</b>

<b>Life Limited Part (LLP) Listing</b>				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 <sup>st</sup> Stg.	3013111	8151	16,840	2,160
Disk, 2 <sup>nd</sup> Stg.	3013712	6Y726	16,672	7,328
Disk, 3 <sup>rd</sup> Stg.	3011713	9986	16,840	8,160
Impeller	3013176	A3980	16,562	2,438
Disk, CT	3013411	A000KX3Y	13,221	2,779
PT Disk, 1 <sup>st</sup> Stg.	3022412	9473	16,840	3,160

Key: TBA = To be assigned, N/A = Not Applicable

<b>Accessories</b>			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-007-01	1753508	0.0
FUEL PUMP	025323-101-02	2890	2,701.9
START FLOW CONTROL	3019109	11734	1,428.0
FUEL CONTROL UNIT	4138008-3	C75512	91.9
OIL/FUEL HEATER	10552E	4473	1,428.0
COMP. BLEED VALVE	3100829-03	A9442	1,428.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.