



**Airforce Turbine Service**  
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368  
 P.O. Box 146 Tynan, TX 78391  
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

<b>Engine Rotor Sheet</b>							
PT6A:	<b>-34</b>	TSN:	<b>9,794.2</b>	TSO:	<b>1,164.2</b>	W/O#:	<b>TBA</b>
PCE:	<b>51005-100</b>	CSN:	<b>10,673</b>	CSO:	<b>2,772</b>	TSHS:	<b>N/A</b>

<b>Life Limited Part (LLP) Listing</b>				
	P/N	S/N	Cycles	
			Consumed	Remaining
<b>PT Disk, 1<sup>st</sup> Stg.</b>	<b>3026812</b>	<b>23B158</b>	<b>19,602</b>	<b>398</b>
Key: TBA = To be assigned, N/A = Not Applicable				

<b>Accessories</b>			
	P/N	S/N	TSO
<b>PROPELLER GOVERNOR</b>	<b>8210-002-01</b>	<b>14413784</b>	<b>1,164.2</b>
Key: TBA = To be assigned, N/A = Not Applicable			

Comments: All engines ship FOB ATS dock.