



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-27I-28	TSN:	15,570.8	TSO:	3,192.0	W/O#:	9692
PCE:	41623	CSN:	16,840	CSO:	1,855	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	82AD45	2,617	16,383
Disk, 2 nd Stg.	3013712	A7060	16,840	7,160
Disk, 3 rd Stg.	3011713	B4069	16,840	8,160
Impeller	3013176	3B703	14,960	4,040
Disk, CT	3013411	A8151	11,350	4,650
PT Disk, 1 st Stg.	3022412	A6368	16,840	3,160

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-004-01	2004879	640.2
FUEL PUMP	025323-101-02	419	3,192.0
FUEL CONTROL UNIT	2524440-9-8-6	A25360	999.6
START FLOW CONTROL	25234-2	12783	3,192.0
OIL/FUEL HEATER	10552E	WA36272	736.1
COMP. BLEED VALVE	3100829-03	7C445	736.1

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.