



**Airforce Turbine Service**  
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368  
 P.O. Box 146 Tynan, TX 78391  
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

<b>Engine Rotor Sheet</b>							
PT6A:	-27I-28	TSN:	14,834.7	TSO:	2,455.9	W/O#:	8162
PCE:	41623	CSN:	16,558	CSO:	1,573	TSHS:	0.0

<b>Life Limited Part (LLP) Listing</b>				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 <sup>st</sup> Stg.	3013111	82AD45	2,335	16,665
Disk, 2 <sup>nd</sup> Stg.	3013712	A7060	16,558	7,442
Disk, 3 <sup>rd</sup> Stg.	3011713	B4069	16,558	8,442
Impeller	3013176	3B703	14,678	4,322
Disk, CT	3013411	A8151	11,068	4,932
PT Disk, 1 <sup>st</sup> Stg.	3022412	A6368	16,558	3,442

Key: TBA = To be assigned, N/A = Not Applicable

<b>Accessories</b>			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-004U	1749494	2,455.9
FUEL PUMP	025323-101-02	419	2,455.9
FUEL CONTROL UNIT	2524440-5	A59639	3,399.06
START FLOW CONTROL	25234-2	12783	2,455.9
OIL/FUEL HEATER	10552E	WA36272	0.0
COMP. BLEED VALVE	3100829-03	7C445	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.