



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-114A	TSN:	5,941.2	TSO:	2,172.4	W/O#:	8972
PCE:	PC1063	CSN:	2,134	CSO:	763	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	85B635	2,134	16,866
Disk, 2 nd Stg.	3013712	A001C8PY	2,134	21,866
Disk, 3 rd Stg.	3011713	A001CBB9	2,134	22,866
Impeller	3027798	9H189	2,134	16,866
Disk, CT	3013411	A001CMBB	2,134	13,866
PT Disk, 1 st Stg.	3026812	A001CPLR	2,134	17,866

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002-01	13494062	2,172.4
FUEL PUMP	702801-5	000829	2,172.4
FUEL CONTROL UNIT	3244897-4	C65649	2,172.4
FLOW DIVIDER	25536-4	21247	2,172.4
OIL/FUEL HEATER	10552E	WA19485	2,172.4
COMP. BLEED VALVE	540-1407-4	3557	2,172.4

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.