



**Airforce Turbine Service**  
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368  
 P.O. Box 146 Tynan, TX 78391  
 Ph: (361) 547-3386 Fx: (361) 547-7273

**ATS Form# 1024**

| <b>Engine Rotor Sheet</b> |       |      |          |      |         |       |     |
|---------------------------|-------|------|----------|------|---------|-------|-----|
| PT6A:                     | -28   | TSN: | 14,097.4 | TSO: | 2,368.0 | W/O#: | N/A |
| PCE:                      | 51543 | CSN: | 13,416   | CSO: | 2,052   | TSHS: | 0.0 |

| <b>Life Limited Part (LLP) Listing</b> |         |          |          |           |
|--|---------|----------|----------|-----------|
|  | P/N     | S/N      | Cycles   |           |
|  |         |          | Consumed | Remaining |
| Hub, 1 <sup>st</sup> Stg.              | 3013111 | A4360    | 13,416   | 5,584     |
| Disk, 2 <sup>nd</sup> Stg.             | 3013712 | A001F975 | 6,513    | 17,487    |
| Disk, 3 <sup>rd</sup> Stg.             | 3011713 | A001F9H8 | 6,513    | 18,487    |
| Impeller                               | 3013176 | 6B374    | 11,316   | 7,684     |
| Disk, CT                               | 3013411 | 2D133    | 4,719    | 11,281    |
| PT Disk, 1 <sup>st</sup> Stg.          | 3022412 | A6923    | 13,416   | 6,584     |

Key: TBA = To be assigned, N/A = Not Applicable

| <b>Accessories</b> |                 |         |         |
|--------------------|-----------------|---------|---------|
|                    | P/N             | S/N     | TSO     |
| PROPELLER GOVERNOR | 8210-002-01     | 1435713 | 608.2   |
| FUEL PUMP          | 025323-101-03   | 8896    | 1,873.3 |
| FUEL CONTROL UNIT  | 2524440-9-8-6   | 25837   | 1,873.3 |
| START FLOW CONTROL | 25234-3         | 9897    | 2,368.0 |
| OIL/FUEL HEATER    | 10552E          | 3727    | 2,368.0 |
| COMP. BLEED VALVE  | 3100829-03 RE71 | 2196    | 2,368.0 |

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.