



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-27/-28	TSN:	18,047.8	TSO:	3,470.7	W/O#:	10385
PCE:	51008	CSN:	24,991	CSO:	7,740	TSHS:	285.4

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	8D567	15,417	3,583
Disk, 2 nd Stg.	3013712	8E779	13,178	10,822
Disk, 3 rd Stg.	3011713	3168	24,690	310
Impeller	3013176	2D973	10,197	8,803
Disk, CT	3013411	A8151	14,037	1,963
PT Disk, 1 st Stg.	3026812	23B158	19,602	398

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002-01	14413784	1,421.4
FUEL PUMP	025323-101-03	12376	1,317.9
FUEL CONTROL UNIT	2524440-9	C7310	3,651.9
START FLOW CONTROL	3019109/25234-2	12047	1,685.9
OIL/FUEL HEATER	10552E	WA12126	877.4
COMP. BLEED VALVE	3100829-03	1A161	1,685.9

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.