



**Airforce Turbine Service**  
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368  
 P.O. Box 146 Tynan, TX 78391  
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

<b>Engine Rotor Sheet</b>							
PT6A:	<b>-34</b>	TSN:	<b>18,055.4</b>	TSO:	<b>3,478.3</b>	W/O#:	<b>TBA</b>
PCE:	<b>51008</b>	CSN:	<b>24,996</b>	CSO:	<b>7,745</b>	TSHS:	<b>818.2</b>

<b>Life Limited Part (LLP) Listing</b>				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 <sup>st</sup> Stg.	3013111	8D567	15,422	3,578
Disk, 2 <sup>nd</sup> Stg.	3013712	8E779	13,183	10,817
Disk, 3 <sup>rd</sup> Stg.	3011713	3168	24,695	305
Impeller	3013176	2D973	10,202	8,798
Disk, CT	3013411	A8151	14,042	1,958
PT Disk, 1 <sup>st</sup> Stg.	3026812	23B158	19,626	393

Key: TBA = To be assigned, N/A = Not Applicable

<b>Accessories</b>			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002-01	19200099	1,094.0
FUEL PUMP	025323-101-03	12376	1,325.5
FUEL CONTROL UNIT	2524440-7-6	A48557	986.2
START FLOW CONTROL	3019109	12047	1,693.5
OIL/FUEL HEATER	10552E	WA12161	885.0
COMP. BLEED VALVE	3100829-03	1A161	1,693.5

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.