



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-114A	TSN:	12,379.4	TSO:	0.0	W/O#:	9330
PCE:	PC1413	CSN:	21,043	CSO:	0.0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	RWA32E691	6,590	12,410
Disk, 2 nd Stg.	3013712	4D438	1,340	22,660
Disk, 3 rd Stg.	3011713	9X260	4,154	20,846
Impeller	3027798	9B182	9,869	9,131
Disk, CT	3013411	A001WC0D	10,595	5,405
PT Disk, 1 st Stg.	3026812	A001PLEC	13,663	6,337

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002-01	15224598	0.0
FUEL PUMP	702801-5	001609	0.0
FUEL CONTROL UNIT	3244897-4	C65615	0.0
FLOW DIVIDER/DUMP VALVE	3019906/25536-4	9959513809	0.0
OIL/FUEL HEATER	10552E	WA11876	0.0
COMP. BLEED VALVE	3049038-3	5458	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.