



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-114A	TSN:	12,611.2	TSO:	231.8	W/O#:	9330
PCE:	PC1413	CSN:	21,238	CSO:	195	TSHS:	231.8

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	RWA32E691	6,785	12,215
Disk, 2 nd Stg.	3013712	4D438	1,535	22,465
Disk, 3 rd Stg.	3011713	9X260	4,349	20,651
Impeller	3027798	9B182	10,064	8,936
Disk, CT	3013411	A001WC0D	10,790	5,210
PT Disk, 1 st Stg.	3026812	A001PLEC	13,858	6,142

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002-01	15224598	231.8
FUEL PUMP	702801-5	001609	231.8
FUEL CONTROL UNIT	3244897-4	C65615	231.8
FLOW DIVIDER	3019906	9959513809	231.8
OIL/FUEL HEATER	10552E	WA11876	231.8
COMP. BLEED VALVE	3019038-03	5458	231.8

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.