



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-41	TSN:	10,035.2	TSO:	3,046.2	W/O#:	TBA
PCE:	80322	CSN:	10,351	CSO:	3,051	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3021911	A1441	10,351	9,649
Disk, 2 nd Stg.	3023112	A3816	10,351	9,649
Disk, 3 rd Stg.	3023113	B4010	10,351	9,649
Impeller	3017463	A1839	10,351	9,649
Disk, CT	3049291-01	A001K2K4	1,876	8,124
PT Disk, 1 st Stg.	3029312	A8305	21,876	8,124
PT Disk, 2 nd Stg.	3029313	3E494	20,784	9,216

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-007G	1148588	0.0
FUEL PUMP	025323-300-02	6268	846.2
FUEL CONTROL UNIT	3244755-22-21-14	A30185	846.2
OIL/FUEL HEATER	10585	399	3,046.2
LP COMP. BLEED VALVE	3100923-02	A4228	3,046.2
HP COMP. BLEED VALVE	3100922-05	A9947	3,046.2

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.