



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-27I-28	TSN:	6,173.2	TSO:	1,757.0	W/O#:	TBA
PCE:	51958	CSN:	6,700	CSO:	1,886	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	6B723	6,700	12,300
Disk, 2 nd Stg.	3013712	9B649	6,700	17,300
Disk, 3 rd Stg.	3011713	9B450	6,700	18,300
Impeller	3013176	4A218	6,700	12,300
Disk, CT	3013411	A2227	6,700	9,300
PT Disk, 1 st Stg.	3022412	1B798	6,700	13,300

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-003U	TBA	3,000
FUEL PUMP	025323-101-02	7057	1,757.0
FUEL CONTROL UNIT	2524440-7-6	TBA	3,000
START FLOW CONTROL	25234-2	10933	1,757.0
OIL/FUEL HEATER	10552E	1561	1,757.0
COMP. BLEED VALVE	3100829-03	3A171	1,757.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.