



**Airforce Turbine Service**  
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368  
 P.O. Box 146 Tynan, TX 78391  
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

<b>Engine Rotor Sheet</b>							
PT6A:	<b>-27I-28</b>	TSN:	<b>6,173.2</b>	TSO:	<b>1,757.0</b>	W/O#:	<b>9539</b>
PCE:	<b>51958</b>	CSN:	<b>6,700</b>	CSO:	<b>1,886</b>	TSHS:	<b>0.0</b>

<b>Life Limited Part (LLP) Listing</b>				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 <sup>st</sup> Stg.	3013111	6B723	6,700	12,300
Disk, 2 <sup>nd</sup> Stg.	3013712	9B649	6,700	17,300
Disk, 3 <sup>rd</sup> Stg.	3011713	9B450	6,700	18,300
Impeller	3013176	4A218	6,700	12,300
Disk, CT	3013411	A6240	8,688	7,312
PT Disk, 1 <sup>st</sup> Stg.	3022412	1B798	6,700	13,300

Key: TBA = To be assigned, N/A = Not Applicable

<b>Accessories</b>			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-003U	TBA	3,000
FUEL PUMP	025323-101-02	7057	1,757.0
FUEL CONTROL UNIT	2524440-7-6	A25292	640.9
START FLOW CONTROL	25234-2	10933	1,757.0
OIL/FUEL HEATER	10552E	1561	1,757.0
COMP. BLEED VALVE	3100829-03	3A171	1,757.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.