



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-27I-28	TSN:	17,947.3	TSO:	1,585.8	W/O#:	TBA
PCE:	50155	CSN:	21,947	CSO:	2,377	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	39B186	5,788	13,212
Disk, 2 nd Stg.	3013712	A5508	11,399	12,601
Disk, 3 rd Stg.	3011713	B2501	11,399	13,601
Impeller	3013176	A7170	11,399	7,601
Disk, CT	3013411	A5843	11,399	4,601
PT Disk, 1 st Stg.	3022412	A5344	11,399	8,601

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-004-01	2477336	1,585.8
FUEL PUMP	025323-101-03	14347	1,585.8
FUEL CONTROL UNIT	2524440-7-6	A66063	1,585.8
START FLOW CONTROL	25234-2	7800	1,585.8
OIL/FUEL HEATER	10552E	5132	1,585.8
COMP. BLEED VALVE	3100829-03	4E378	1,585.8

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.