



Airforce Turbine Service
www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fax: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-34	TSN:	25,323.4	TSO:	0.0	W/O#:	TBA
PCE:	41582	CSN:	31,848	CSO:	0.0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	24A823	14,851	4,149
Disk, 2 nd Stg.	3013712	9L593	8,498	15,502
Disk, 3 rd Stg.	3013713	348135	9,966	15,034
Impeller	3013176	A7326	12,373	6,627
Disk, CT	3013411	4W420	10,366	5,634
PT Disk, 1 st Stg.	3026812	A001XL001	14,990	5,010

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002	TBA	0.0
FUEL PUMP	025323-101-02	12457	0.0
FUEL CONTROL UNIT	2524440-7-6	A25676	0.0
START FLOW CONTROL	25234-2	8843	0.0
OIL/FUEL HEATER	10552E	5-20-96	0.0
COMP. BLEED VALVE	3100829-03	2H343	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.