



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

| Engine Rotor Sheet | | | | | | | |
|---------------------------|--------------|------|---------------|------|----------------|-------|-------------|
| PT6A: | -34 | TSN: | 10,451 | TSO: | 3,485.0 | W/O#: | 9409 |
| PCE: | 52151 | CSN: | 12,060 | CSO: | 4,889 | TSHS: | 0.0 |

| Life Limited Part (LLP) Listing | | | | |
|--|---------|----------|----------|-----------|
| | P/N | S/N | Cycles | |
| | | | Consumed | Remaining |
| Hub, 1 st Stg. | 3013111 | 9C931 | 12,060 | 6,940 |
| Disk, 2 nd Stg. | 3013712 | 7D533 | 12,060 | 11,940 |
| Disk, 3 rd Stg. | 3011713 | 6C296 | 12,060 | 12,940 |
| Impeller | 3013176 | 7A461 | 12,060 | 6,940 |
| Disk, CT | 3013411 | A00004N2 | 15,399 | 601 |
| PT Disk, 1 st Stg. | 3022412 | 7C695 | 12,060 | 7,940 |

Key: TBA = To be assigned, N/A = Not Applicable

| Accessories | | | |
|--------------------|---------------|--------|---------|
| | P/N | S/N | TSO |
| PROPELLER GOVERNOR | 8210-002-01 | 983056 | 269.2 |
| FUEL PUMP | 025323-101-02 | 7979 | 3,485.0 |
| FUEL CONTROL UNIT | 252444-0-7-6 | A25113 | 1,741.7 |
| START FLOW CONTROL | 3019109 | 13301 | 3,485.0 |
| OIL/FUEL HEATER | 10552E | 1129 | 3,485.0 |
| COMP. BLEED VALVE | 3100829-03 | 8F793 | 3,485.0 |

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.