



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fax: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-114A	TSN:	6,792.9	TSO:	3,185.6	W/O#:	9590
PCE:	PC0805	CSN:	9,966	CSO:	6,773	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	1X196	11,056	7,944
Disk, 2 nd Stg.	3013712	A6288	14,835	9,165
Disk, 3 rd Stg.	3011713	A000D3NE	9,966	15,034
Impeller	3027798	5H706	9,966	9,034
Disk, CT	3013411	A001WC0D	10,790	5,210
PT Disk, 1 st Stg.	3026812	A002WTP1	15,396	4,604

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002-01	2000544	66.3
FUEL PUMP	025323-150	1041	66.3
FUEL CONTROL UNIT	3244897-4	C65825	3,185.6
FLOW DIVIDER	3019906	9959558238	66.3
OIL/FUEL HEATER	10552E	WA14546	3,185.6
COMP. BLEED VALVE	540-1407-4	GA1451	3,185.6

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS doc