



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fax: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	114A	TSN:	6,726.6	TSO:	3,119.3	W/O#:	9590
PCE:	PC0805	CSN:	9,878	CSO:	6,685	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	1X196	10,968	8,032
Disk, 2 nd Stg.	3013712	A6288	14,747	9,253
Disk, 3 rd Stg.	3011713	A000D3NE	9,878	15,122
Impeller	3027798	5H706	9,878	9,122
Disk, CT	3013411	YUAA006A642	15,396	604
PT Disk, 2 nd Stg.	3026812	A000C6LF	9,878	10,122

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002-01	2000544	0.0
FUEL PUMP	025323-150	1041	0.0
FUEL CONTROL UNIT	3244897-4	C65825	3,119.3
FLOW DIVIDER	3019906	9959558238	0.0
OIL/FUEL HEATER	10552E	WA14546	3,119.3
COMP. BLEED VALVE	540-1407-4	GA1451	3,119.3

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS doc.