



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fax: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	114A	TSN:	6,712.5	TSO:	2,938.4	W/O#:	TBA
PCE:	PC1002	CSN:	N/A	CSO:	N/A	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	77B126	11,104	7,896
Disk, 2 nd Stg.	3013712	A0017805	11,104	12,896
Disk, 3 rd Stg.	3013713	A00177YB	11,104	13,896
Impeller	3027798	TX1A2322	11,104	7,896
Disk, CT	3013411	A0017L8W	9,302	6,698
PT Disk, 1st Stg.	3026812	A0017R3C	9,302	10,698

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002-01	13296411	2,938.4
FUEL PUMP	702801-5	000742	2,938.4
FUEL CONTROL UNIT	3244897-4	C65589	2,938.4
START FLOW DIVIDER	25536-4	21002	2,938.4
OIL/FUEL HEATER	100552E	WA18700	2,938.4
COMP. BLEED VALVE	540-1407-4	3354	2,938.4

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.