



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-15AG	TSN:	7,419.8	TSO:	N/A	W/O#:	TBA
PCE:	14222	CSN:	N/A	CSO:	N/A	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	30A010	2,085	16,915
Disk, 2 nd Stg.	3013712	59A721	6,450	17,550
Disk, 3 rd Stg.	3011713	59A756	5,480	19,520
Impeller	3013176	54A153	4,102	14,898
Disk, CT	3013411	9B060	10,831	5,169
PT Disk, 1 st Stg.	3022412	4E897	3,226	16,774

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002AE	2334263	2,232.7
FUEL PUMP	025323-101-03	14880	2,232.7
FUEL CONTROL UNIT	3244786-6	B32180	2,232.7
START FLOW CONTROL	3019109	14740	7,419.8
OIL/FUEL HEATER	10552E	WA1782	7,419.8
COMP. BLEED VALVE	3100829-03	10A585	2,232.7

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.