



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-21	TSN:	GG: 1,136.0 PS: 1,136.0	TSO:	GG: N/A PS: 0.0	W/O#:	TBA
PCE:	PE0663	CSN:	GG: 1,045 PS: 1,045	CSO:	GG: N/A PS: 0.0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	RWA14A062	1,045	17,955
Disk, 2 nd Stg.	3013712	A001RKPE	1,045	22,955
Disk, 3 rd Stg.	3011713	A001T027	1,045	23,955
Impeller	3013176	EAAA000L518	1,045	17,955
Disk, CT	3013411	A001T9W3	1,045	14,955
PT Disk, 1 st Stg.	3026812	A001RTH1	1,045	18,955

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002	14413748AE	1,136.0
FUEL PUMP	386101-5	002316	1,136.0
FUEL CONTROL UNIT	3244775-7 RE24	C21049	1,136.0
FLOW DIVIDER	25536-4	9959512508	1,136.0
OIL/FUEL HEATER	10552E	WA22628	1,136.0
COMP. BLEED VALVE	3100829-03	1R268	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.