



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-34	TSN:	14,097.4	TSO:	2,368.0	W/O#:	N/A
PCE:	51543	CSN:	13,416	CSO:	2,052	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	A4360	13,416	5,584
Disk, 2 nd Stg.	3013712	A001F975	6,513	17,487
Disk, 3 rd Stg.	3011713	A001F9H8	6,513	18,487
Impeller	3013176	6B374	11,316	7,684
Disk, CT	3013411	2D133	4,719	11,281
PT Disk, 1 st Stg.	3022412	A6923	13,416	6,584

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002-01	1435713	608.2
FUEL PUMP	025323-101-03	8896	1,873.3
FUEL CONTROL UNIT	2524440-9-8-6	25837	1,873.3
START FLOW CONTROL	25234-3	9897	2,368.0
OIL/FUEL HEATER	10552E	3727	2,368.0
COMP. BLEED VALVE	3100829-03 RE71	2196	2,368.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.