



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

| Engine Rotor Sheet | | | | | | | |
|---------------------------|--------------|------|----------------------------|------|----------------------------|-------|------------|
| PT6A: | -34 | TSN: | GG: 7,910.2 PS: 7,853.8 | TSO: | GG: 3,159.2 PS: 3,102.8 | W/O#: | N/A |
| PCE: | 51990 | CSN: | GG: 6,366 PS: 6,760 | CSO: | GG: 2,944 PS: 3,338 | TSHS: | 0.0 |

| Life Limited Part (LLP) Listing | | | | |
|--|---------|--------|----------|-----------|
| | P/N | S/N | Cycles | |
| | | | Consumed | Remaining |
| Hub, 1 st Stg. | 3013111 | 06B777 | 6,366 | 12,634 |
| Disk, 2 nd Stg. | 3013712 | 09B672 | 6,366 | 17,634 |
| Disk, 3 rd Stg. | 3011713 | 09B520 | 6,366 | 18,634 |
| Impeller | 3013176 | 05A595 | 6,366 | 12,634 |
| Disk, CT | 3013411 | 08B984 | 6,366 | 9,634 |
| PT Disk, 1 st Stg. | 3022412 | 08B367 | 6,760 | 13,240 |

Key: TBA = To be assigned, N/A = Not Applicable

| Accessories | | | |
|--------------------|--------------|---------|---------|
| | P/N | S/N | TSO |
| PROPELLER GOVERNOR | T8210-003U | 2168073 | 4,447.2 |
| FUEL PUMP | 025323-101-3 | 7072D | 1,662.7 |
| FUEL CONTROL UNIT | 2524440-9 | C7179 | 1,662.7 |
| START FLOW CONTROL | 3019109 | 11939 | 1,662.7 |
| OIL/FUEL HEATER | 10552E | 2918 | 1,662.7 |
| COMP. BLEED VALVE | 3100829-03 | 3H153 | 629.8 |

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.