



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-27I-28	TSN:	16,405.3	TSO:	0.0	W/O#:	TBA
PCE:	PG0145	CSN:	24,886	CSO:	0.0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	RWA00C698	5,954	13,046
Disk, 2 nd Stg.	3013712	A002H7L6	5,954	18,046
Disk, 3 rd Stg.	3011713	A0027RY0	5,954	19,046
Impeller	3013176	EAAB000L247	5,954	13,046
Disk, CT	3013411	YUAA003A284	5,954	10,046
PT Disk, 1 st Stg.	3026812	A002HN71	5,954	14,046

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-004-01	1432572	0.0
FUEL PUMP	386101-5	1392	0.0
FUEL CONTROL UNIT	2524440-9-8-6	A66634	0.0
START FLOW CONTROL	25234-5	15341	0.0
OIL/FUEL HEATER	10552E	8265	0.0
COMP. BLEED VALVE	3100829-03	39A475	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.

Note: In compliance with P&WC SB1803 (TBO Extension)