



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-27/-28	TSN:	34,997.3	TSO:	0.0	W/O#:	9443
PCE:	41169	CSN:	50,019	CSO:	0.0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	85B900	5,376	13,624
Disk, 2 nd Stg.	3013712	A000MX0N	11,723	12,277
Disk, 3 rd Stg.	3011713	A0011X3B	11,723	13,277
Impeller	3013176	TXA1A4856	5,376	13,624
Disk, CT	3013411	A000W4K0	11,723	4,277
PT Disk, 1 st Stg.	3026812	A001LDRT	5,376	14,624

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-004-01	TBA	0.0
FUEL PUMP	025323-101	7433	0.0
FUEL CONTROL UNIT	2524440-5	A41212	0.0
START FLOW CONTROL	3019109	10560	0.0
OIL/FUEL HEATER	3011475	591	0.0
COMP. BLEED VALVE	3029174	A5957	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.