



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-27/-28	TSN:	15,549.0	TSO:	0.0	W/O#:	9705
PCE:	50157	CSN:	16,835	CSO:	0.0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	1D944	7,618	11,382
Disk, 2 nd Stg.	3013712	3295	16,835	7,165
Disk, 3 rd Stg.	3011713	4892	16,835	8,165
Impeller	3013176	TBA	10,500	8,500
Disk, CT	3013411	7A719	11,233	4,767
PT Disk, 1 st Stg.	3026812	A0001MAB	12,308	7,692

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002	TBA	0.0
FUEL PUMP	025323-101-03	12860	0.0
FUEL CONTROL UNIT	252444-7-6	A66724	0.0
START FLOW CONTROL	3019109	TBA	0.0
OIL/FUEL HEATER	10552E	3197	0.0
COMP. BLEED VALVE	3100829-03	A6466	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.