



**Airforce Turbine Service**  
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368  
 P.O. Box 146 Tynan, TX 78391  
 Ph: (361) 547-3386 Fx: (361) 547-7273

**ATS Form# 1024**

<b>Engine Rotor Sheet</b>							
PT6A:	-27/-28	TSN:	8,898.2	TSO:	1,910.6	W/O#:	9953
PCE:	51472	CSN:	10,434	CSO:	1,816	TSHS:	0.0

<b>Life Limited Part (LLP) Listing</b>				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 <sup>st</sup> Stg.	3013111	A4124	10,434	8,566
Disk, 2 <sup>nd</sup> Stg.	3013712	A001EENM	1,816	22,184
Disk, 3 <sup>rd</sup> Stg.	3011713	A001EF9A	1,816	23,184
Impeller	3013176	AB804	7,472	11,528
Disk, CT	3013411	A2243	10,434	5,566
PT Disk, 1 <sup>st</sup> Stg.	3022412	A6833	10,434	9,566

Key: TBA = To be assigned, N/A = Not Applicable

<b>Accessories</b>			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-003	2243687	1,910.6
FUEL PUMP	025323-101-03	1168	1,910.6
FUEL CONTROL UNIT	2524440-9-8-6	A48914	1,910.6
START FLOW CONTROL	25234-2	9777	1,910.6
OIL/FUEL HEATER	10552E	3556	1,910.6
COMP. BLEED VALVE	3100829-03	4B648	1,910.6

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.