



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-27/-28	TSN:	8,898.2	TSO:	1,910.6	W/O#:	9954
PCE:	51475	CSN:	10,434	CSO:	1,816	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	A4085	10,434	8,566
Disk, 2 nd Stg.	3013712	A001EENL	1,816	22,184
Disk, 3 rd Stg.	3011713	A001EF9F	1,816	23,184
Impeller	3013176	B0443	10,434	8,566
Disk, CT	3013411	A2241	10,434	5,566
PT Disk, 1 st Stg.	3022412	A6836	10,434	9,566

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-003U	2243919	1,910.6
FUEL PUMP	025323-101-02	5465	1,910.6
FUEL CONTROL UNIT	2524440-9-8-6	A7380	1,910.6
START FLOW CONTROL	25234-2	12662	1,133.2
OIL/FUEL HEATER	10552E	3558	1,910.6
COMP. BLEED VALVE	3100829-03	A8676	1,910.6

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.