



**Airforce Turbine Service**  
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368  
 P.O. Box 146 Tynan, TX 78391  
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

<b>Engine Rotor Sheet</b>							
PT6A:	<b>-34</b>	TSN:	<b>15,549.0</b>	TSO:	<b>0.0</b>	W/O#:	<b>9705</b>
PCE:	<b>50157</b>	CSN:	<b>16,835</b>	CSO:	<b>0.0</b>	TSHS:	<b>0.0</b>

<b>Life Limited Part (LLP) Listing</b>				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 <sup>st</sup> Stg.	3013111	1D944	7,618	11,382
Disk, 2 <sup>nd</sup> Stg.	3013712	3295	16,835	7,165
Disk, 3 <sup>rd</sup> Stg.	3011713	4892	16,835	8,165
Impeller	3013176	TBA	10,500	8,500
Disk, CT	3013411	7A719	11,233	4,767
PT Disk, 1 <sup>st</sup> Stg.	3026812	A0001MAB	12,308	7,692

Key: TBA = To be assigned, N/A = Not Applicable

<b>Accessories</b>			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002	TBA	0.0
FUEL PUMP	025323-101-03	12860	0.0
FUEL CONTROL UNIT	252444-7-6	A66724	0.0
START FLOW CONTROL	3019109	TBA	0.0
OIL/FUEL HEATER	10552E	3197	0.0
COMP. BLEED VALVE	3100829-03	A6466	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.