



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-34AG	TSN:	4,534.9	TSO:	0.0	W/O#:	TBA
PCE:	PH0961	CSN:	Starts: 2,127 Flights: 9,187	CSO:	0.0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	RWA99D395	1,522	14,748
Disk, 2 nd Stg.	3013712	A003B54W	4,707	19,293
Disk, 3 rd Stg.	3011713	A003B34T	3,999	21,001
Impeller	3013176	EAAD000B544	2,998	16,002
Disk, CT	3013411	YUAA015A804	4,958	11,042
PT Disk, 1 st Stg.	3026812	YUAA015A873	2,833	21,167

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSN
PROPELLER GOVERNOR	8210-002-01	18852434	0.0
FUEL PUMP	386101-5	003874	0.0
FUEL CONTROL UNIT	4138008-3	C76130	0.0
FLOW DIVIDER	3019906	L0238	0.0
OIL/FUEL HEATER	10552E	WA45066	0.0
COMP. BLEED VALVE	3075033-01	AHX013203	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.