



**Airforce Turbine Service**  
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368  
 P.O. Box 146 Tynan, TX 78391  
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

<b>Engine Rotor Sheet</b>							
PT6A:	<b>-34AG</b>	TSN:	<b>4,549.2</b>	TSO:	<b>112.3</b>	W/O#:	<b>TBA</b>
PCE:	<b>PH0877</b>	CSN:	Starts: 3,565 Flights: 7,979	CSO:	Starts: 56 Flights: 203	TSHS:	<b>0.0</b>

<b>Life Limited Part (LLP) Listing</b>				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 <sup>st</sup> Stg.	3013111	RWA78D615	1,913	17,087
Disk, 2 <sup>nd</sup> Stg.	3013712	A00393RP	5,916	18,084
Disk, 3 <sup>rd</sup> Stg.	3011713	A0038K8R	5,027	19,973
Impeller	3013176	EAAC000Y409	3,060	15,940
Disk, CT	3013411	YUAA012A744	7,011	8,898
PT Disk, 1 <sup>st</sup> Stg.	3026812	YUAA012A152	4,007	19,993

Key: TBA = To be assigned, N/A = Not Applicable

<b>Accessories</b>			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002-01	18479985	112.3
FUEL PUMP	386101-5	003673	112.3
FUEL CONTROL UNIT	4138008-3 MOD 4	C75985	112.3
OIL/FUEL HEATER	10552E	WA44237	112.3
COMP. BLEED VALVE	3075033	AHX1500504	112.3

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.