



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-114A	TSN:	6,314.2	TSO:	2,376.0	W/O#:	TBD
PCE:	PC0883	CSN:	7,082	CSO:	2,736	TSHS:	606.3

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	70B273	7,082	11,918
Disk, 2 nd Stg.	3013712	A000T5MK	7,082	16,918
Disk, 3 rd Stg.	3011713	A000T5NF	7,082	17,918
Impeller	3027798	8H029	7,082	11,918
Disk, CT	3013411	A000RWPE	7,082	8,918
PT Disk, 1 st Stg.	3026812	A000T5X6	7,082	12,918

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002-01	13039152	2,376.0
FUEL PUMP	3034792	0603	2,376.0
FUEL CONTROL UNIT	3244897-4	C66069	3,397.8
FLOW DIVIDER	3019906D	20615	2,376.0
OIL/FUEL HEATER	3032710	WA16602	2,376.0
COMP. BLEED VALVE	3049038-03	4387	2,376.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.
 -SR, 1/15/21