



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-21	TSN:	7,122.5	TSO:	0.0	W/O#:	10019
PCE:	24416	CSN:	7,233	CSO:	0.0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	A3486	7,233	11,767
Disk, 2 nd Stg.	3013712	6572	7,233	16,767
Disk, 3 rd Stg.	3011713	3714	7,233	17,767
Impeller	3013176	A9765	7,233	11,767
Disk, CT	3013411	A9030	7,233	8,767
PT Disk, 1 st Stg.	3022412	A5949	7,233	12,767

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002AD	1201066AD	0.0
FUEL PUMP	025323-101-03	9056	0.0
FUEL CONTROL UNIT	3244745-2	A33143	0.0
FLOW DIVIDER	3019906	3522	0.0
OIL/FUEL HEATER	10552E	2990	0.0
COMP. BLEED VALVE	3100829-03	3A552	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.