



**Airforce Turbine Service**  
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368  
 P.O. Box 146 Tynan, TX 78391  
 Ph: (361) 547-3386 Fx: (361) 547-7273

**ATS Form# 1024**

<b>Engine Rotor Sheet</b>							
PT6A:	<b>-21</b>	TSN:	<b>7,122.5</b>	TSO:	<b>0.0</b>	W/O#:	<b>10020</b>
PCE:	<b>24421</b>	CSN:	<b>7,233</b>	CSO:	<b>0</b>	TSHS:	<b>0.0</b>

<b>Life Limited Part (LLP) Listing</b>				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 <sup>st</sup> Stg.	3013111	A3421	7,233	11,767
Disk, 2 <sup>nd</sup> Stg.	3013712	A6538	7,233	16,767
Disk, 3 <sup>rd</sup> Stg.	3011713	B3754	7,233	17,767
Impeller	3013176	A9738	7,233	11,767
Disk, CT	3013411	2B325	7,849	8,151
PT Disk, 1 <sup>st</sup> Stg.	3026812	SA000DBWX	1,531	18,469
Key: TBA = To be assigned, N/A = Not Applicable				

<b>Accessories</b>			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002AD	1201107V	0.0
FUEL PUMP	025323-101-02	4284	0.0
FUEL CONTROL UNIT	97-380000-15	1186	0.0
FLOW DIVIDER	3019906	3770	0.0
OIL/FUEL HEATER	10552E	3173	0.0
COMP. BLEED VALVE	3100829-03	5A471	0.0
Key: TBA = To be assigned, N/A = Not Applicable			

Comments: All engines ship FOB ATS dock.