



**Airforce Turbine Service**  
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368  
 P.O. Box 146 Tynan, TX 78391  
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

<b>Engine Rotor Sheet</b>							
PT6A:	<b>-34AG</b>	TSN:	<b>2,849.4</b>	TSO:	<b>0.0</b>	W/O#:	<b>10111</b>
PCE:	<b>PH1096</b>	CSN:	<b>N/A</b>	CSO:	<b>N/A</b>	TSHS:	<b>0.0</b>

<b>Life Limited Part (LLP) Listing</b>				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 <sup>st</sup> Stg.	3013111	RWA49E951	1,497	17,503
Disk, 2 <sup>nd</sup> Stg.	3013712	A003KKB3	4,629	19,371
Disk, 3 <sup>rd</sup> Stg.	3011713	A003KKBP	3,933	21,067
Impeller	3013176	CRAZAEPN042	2,154	16,846
Disk, CT	3013411	CRAZAENY451	5,750	10,250
PT Disk, 1 <sup>st</sup> Stg.	3026812	YUAB001C546	3,286	20,714

Key: TBA = To be assigned, N/A = Not Applicable

<b>Accessories</b>			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002-01	19720008	0.0
FUEL PUMP	386100	004240	0.0
FUEL CONTROL UNIT	4138008-3	C76185	0.0
FLOW DIVIDER	3019906	L0757	0.0
OIL/FUEL HEATER	10552E	WA50296	0.0
COMP. BLEED VALVE	3105436-01	AHX1501211	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.