



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-34AG	TSN:	2,849.4	TSO:	N/A	W/O#:	10111
PCE:	PH1096	CSN:	STARTS-3,091 FLIGHTS-5,039	CSO:	N/A	TSHS:	N/A

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	RWA49E951	1,497	17,503
Disk, 2 nd Stg.	3013712	A003KKB3	4,629	19,371
Disk, 3 rd Stg.	3011713	A003KKBP	3,933	21,067
Impeller	3013176	CRAZAEPN042	2,154	16,846
Disk, CT	3013411	CRAZAENY451	5,750	10,250
PT Disk, 1 st Stg.	3026812	YUAB001C546	3,286	20,714

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002-01	19720008	N/A
FUEL PUMP	386100	004240	N/A
FUEL CONTROL UNIT	4138008-3	C76380	N/A
FLOW DIVIDER	3019906	L0757	N/A
OIL/FUEL HEATER	10552E	WA50296	N/A
COMP. BLEED VALVE	3105436-01	AHX1501211	N/A

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.