



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fax: (361) 547-7273

ATS Form# 1024

| Engine Rotor Sheet | | | | | | | |
|---------------------------|--------------|------|-----------------|------|------------|-------|-------------|
| PT6A: | -34 | TSN: | 34,997.3 | TSO: | 0.0 | W/O#: | 9443 |
| PCE: | 41169 | CSN: | 50,019 | CSO: | 0 | TSHS: | 0.0 |

| Life Limited Part (LLP) Listing | | | | |
|--|---------|-----------|----------|-----------|
| | P/N | S/N | Cycles | |
| | | | Consumed | Remaining |
| Hub, 1 st Stg. | 3013111 | 85B900 | 5,376 | 13,624 |
| Disk, 2 nd Stg. | 3013712 | A000MX0N | 11,723 | 12,277 |
| Disk, 3 rd Stg. | 3011713 | A0011X3B | 11,723 | 13,277 |
| Impeller | 3013176 | TXA1A4856 | 5,376 | 13,624 |
| Disk, CT | 3013411 | A000W4K0 | 11,723 | 4,277 |
| PT Disk, 1 st Stg. | 3026812 | A001LDRT | 5,376 | 14,624 |

Key: TBA = To be assigned, N/A = Not Applicable

| Accessories | | | |
|--------------------|-------------|--------|-----|
| | P/N | S/N | TSO |
| PROPELLER GOVERNOR | 8210-004-01 | TBA | 0.0 |
| FUEL PUMP | 025323-101 | 7433 | 0.0 |
| FUEL CONTROL UNIT | 2524440-5 | A41212 | 0.0 |
| START FLOW CONTROL | 3019109 | 10560 | 0.0 |
| OIL/FUEL HEATER | 3011475 | 591 | 0.0 |
| COMP. BLEED VALVE | 3029174 | A5957 | 0.0 |

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS Dock