



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

| Engine Rotor Sheet | | | | | | | |
|---------------------------|--------|------|----------|------|-----|-------|-------|
| PT6A: | -34 | TSN: | 15,636.9 | TSO: | 0.0 | W/O#: | 10288 |
| PCE: | PG0033 | CSN: | 24,997 | CSO: | 0 | TSHS: | 0.0 |

| Life Limited Part (LLP) Listing | | | | |
|---|---------|-------------|----------|-----------|
| | P/N | S/N | Cycles | |
| | | | Consumed | Remaining |
| Hub, 1 st Stg. | 3013111 | RWA48D559 | 6,176 | 12,824 |
| Disk, 2 nd Stg. | 3013712 | A0032K8A | 6,176 | 17,824 |
| Disk, 3 rd Stg. | 3011713 | A00130AE | 9,524 | 15,476 |
| Impeller | 3013176 | TXA1C7157 | 6,176 | 12,824 |
| Disk, CT | 3013411 | 7A719 | 11,233 | 4,767 |
| PT Disk, 1 st Stg. | 3026812 | YUAA010A456 | 6,176 | 13,824 |
| Key: TBA = To be assigned, N/A = Not Applicable | | | | |

| Accessories | | | |
|---|---------------|---------|-----|
| | P/N | S/N | TSO |
| PROPELLER GOVERNOR | 8210-004-01 | 1151402 | 0.0 |
| FUEL PUMP | 025323-101-01 | 10169 | 0.0 |
| FUEL CONTROL UNIT | 2524440-9-8-6 | A59790 | 0.0 |
| OIL/FUEL HEATER | 10552E | WA12780 | 0.0 |
| COMP. BLEED VALVE | 3100829-03 | 43A053 | 0.0 |
| Key: TBA = To be assigned, N/A = Not Applicable | | | |

Comments: All engines ship FOB ATS dock.