



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-34	TSN:	15,649.2	TSO:	0.0	W/O#:	10291
PCE:	PG0034	CSN:	24,954	CSO:	0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	RWA39D665	6,188	12,812
Disk, 2 nd Stg.	3013712	A0032W02	6,188	17,812
Disk, 3 rd Stg.	3011713	3H385	9,551	15,449
Impeller	3013176	TXA1C7148	6,188	12,812
Disk, CT	3013411	9B060	10,831	5,169
PT Disk, 1 st Stg.	3026812	YUAA010A406	6,188	13,812
Key: TBA = To be assigned, N/A = Not Applicable				

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-004-01	1200166	0.0
FUEL PUMP	386101-5	0207	0.0
FUEL CONTROL UNIT	2524440-9-8-6	A85379	0.0
OIL/FUEL HEATER	10552E	3099	0.0
COMP. BLEED VALVE	3100829-03	6D431	0.0
Key: TBA = To be assigned, N/A = Not Applicable			

Comments: All engines ship FOB ATS dock.