



11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-67D	TSN:	20,628.6	TSO:	5,544.4	W/O#:	10465
PCE:	114043	CSN:	31,517	CSO:	8,178	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3039001	41B963	18,783	5,217
Disk, 2 nd Stg.	3040952	69B572	8,178	15,822
Disk, 3 rd Stg.	3040933	69B880	8,178	15,822
Disk, 4 th Stg.	3040944	70B392	8,178	15,822
Rotor Shaft	3043063	A000MW67	8,178	15,822
Impeller	3036898	7H444	8,178	15,822
Disk, CT	3040911	A0005W72	6,352	1,648
PT Disk, 1 st Stg.	3037312	A000P6HA	8,178	6,822
PT Disk, 2 nd Stg.	3037313	A000PNR4	8,178	6,822

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-410	11448781	946.5
FUEL PUMP	399701-5	0271	5,544.4
FUEL CONTROL UNIT	8063-005B	11892452	5,544.4
FLOW DIVIDER	26130-2	0440	5,544.4
OIL/FUEL HEATER	10585J	1020	5,544.4
COMP. BLEED VALVE	3123532-01	40A561	5,544.4

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.