



**Airforce Turbine Service**  
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368  
 P.O. Box 146 Tynan, TX 78391  
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

<b>Engine Rotor Sheet</b>							
PT6A:	<b>-114A</b>	TSN:	<b>5,149.4</b>	TSO:	<b>0.0</b>	W/O#:	<b>TBD</b>
PCE:	<b>PC2148</b>	CSN:	<b>12,063</b>	CSO:	<b>0.0</b>	TSHS:	<b>0.0</b>

<b>Life Limited Part (LLP) Listing</b>				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 <sup>st</sup> Stg.	3013111	RWA63E648	12,063	6,937
Disk, 2 <sup>nd</sup> Stg.	3013712	A003LL1H	12,063	11,937
Disk, 3 <sup>rd</sup> Stg.	3011713	A003LWTC	12,063	12,937
Impeller	3027798	CRAZAERU105	12,063	6,937
Disk, CT	3013411	CRAZAERB353	12,063	3,937
PT Disk, 1 <sup>st</sup> Stg.	3026812	YUAB001C518	12,063	7,937

Key: TBA = To be assigned, N/A = Not Applicable

<b>Accessories</b>			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002-01	18965567	0.0
FUEL PUMP	702801-5	003832	0.0
FUEL CONTROL UNIT	3244897-4	C66785	0.0
FLOW DIVIDER	25536-4	18305	0.0
OIL/FUEL HEATER	3032710	WA50435	0.0
COMP. BLEED VALVE	540-1407-4	8307	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.