



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-21	TSN:	3,427.5	TSO:	0.0	W/O#:	TBD
PCE:	PE0129	CSN:	4,358	CSO:	0.0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	49B614	4,358	14,642
Disk, 2 nd Stg.	3013712	51B525	4,358	19,642
Disk, 3 rd Stg.	3011713	51B509	4,358	20,642
Impeller	3013176	9F352	4,358	14,642
Disk, CT	3013411	52B203	4,358	11,642
PT Disk, 1 st Stg.	3022412	50B559	4,358	15,642

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-025G	12011850	0.0
FUEL PUMP	3034794	0714	0.0
FUEL CONTROL UNIT	3027049	C17337	0.0
START FLOW CONTROL	3036640	2870	0.0
OIL/FUEL HEATER	3032710	WA10015	0.0
COMP. BLEED VALVE	3100829-03	18A230	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.