



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-34	TSN:	9,943.9	TSO:	0.0	W/O#:	9945
PCE:	51519	CSN:	14,534	CSO:	0.0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	2B187	12,972	6,028
Disk, 2 nd Stg.	3013712	A7379	14,534	9,466
Disk, 3 rd Stg.	3011713	B5129	14,534	10,466
Impeller	3013176	7E236	12,669	6,331
Disk, CT	3013411	7E790	7,902	8,098
PT Disk, 1 st Stg.	3022412	74A471	11,984	8,016

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002	TBA	0.0
FUEL PUMP	025323-101-02	14962	0.0
FUEL CONTROL UNIT	2524440-9-8-6	308481	0.0
START FLOW CONTROL	3019109	7086	0.0
OIL/FUEL HEATER	10552E	3656	0.0
COMP. BLEED VALVE	3100829-03	7C154	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.