



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-34	TSN:	2,047.2	TSO:	NA	W/O#:	10908
PCE:	RB0075	CSN:	2,099	CSO:	NA	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	65B527	2,099	16,901
Disk, 2 nd Stg.	3013712	A000BYKT	2,099	21,901
Disk, 3 rd Stg.	3011713	A000CB4N	2,099	22,901
Impeller	3013176	5H362	2,099	16,901
Disk, CT	3013411	A000C6HH	2,099	13,901
PT Disk, 1 st Stg.	3026812	A000C6LN	2,099	17,901

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-304	15267662	5.9
FUEL PUMP	3034794	1293	2,047.2
FUEL CONTROL UNIT	N/A	N/A	N/A
FLOW DIVIDER/DUMP VALVE	3019906/25536-4	16268	0.0
OIL/FUEL HEATER	3032710	WA14348	2,047.2
COMP. BLEED VALVE	3100829-03	35A580	2,047.2

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.