



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-34	TSN:	2,047.2	TSO:	NA	W/O#:	TBD
PCE:	RB0078	CSN:	2,099	CSO:	NA	TSHS:	111.3

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	61B797	2,099	16,901
Disk, 2 nd Stg.	3013712	A000CW28	2,099	21,901
Disk, 3 rd Stg.	3011713	A000D3P4	2,099	22,901
Impeller	3013176	5H359	2,099	16,901
Disk, CT	3013411	A000CW28	2,099	13,901
PT Disk, 1 st Stg.	3026812	A000DBXB	2,099	17,901

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	3035927	12198693U	2,047.2
FUEL PUMP	3034794	1326	2,047.2
FUEL CONTROL UNIT	CUSTOMER SUPPLIED	CUSTOMER SUPPLIED	TBD
START FUEL CONTROL	3019109	15318	2,047.2
OIL/FUEL HEATER	3032710	WA14577	2,047.2
COMP. BLEED VALVE	3100829-03	39A152	2,047.2

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.