



Airforce Turbine Service
www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-27/-28	TSN:	13,097.1	TSO:	0.0	W/O#:	11594
PCE:	41375	CSN:	16,301	CSO:	0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	6069	14,533	4,467
Disk, 2 nd Stg.	3013712	A3648	16,301	7,699
Disk, 3 rd Stg.	3011713	8948	16,301	8,699
Impeller	3013176	6A309	14,729	4,271
Disk, CT	3013411	3Y170	13,250	2,750
PT Disk, 1 st Stg.	3022412	9P215	14,200	5,800
Key: TBA = To be assigned, N/A = Not Applicable				

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002-01	158237	0.0
FUEL PUMP	386101-5	1190	0.0
FUEL CONTROL UNIT	2524440-9	C7377	0.0
START FLOW CONTROL	25234-5	9959538107	0.0
OIL/FUEL HEATER	10552E	3262	0.0
COMP. BLEED VALVE	3100829-03	A9723	0.0
Key: TBA = To be assigned, N/A = Not Applicable			

Comments: All engines ship FOB ATS dock.