



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-114A	TSN:	4,407.2	TSO:	0.0	W/O#:	11882
PCE:	PC1656	CSN:	Starts: 2,636 Flights: 3,513	CSO:	0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	RWA14C480	3,075	15,925
Disk, 2 nd Stg.	3013712	A002KA5Y	3,075	20,925
Disk, 3 rd Stg.	3011713	A002K38P	3,075	21,925
Impeller	3027798	EAAB000T137	3,075	15,925
Disk, CT	3013411	CRAZAENY466	397	15,603
PT Disk, 1 st Stg.	3026812	A002L2C2	2,811	17,189

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROP GOVERNOR	8210-002-01	1949167AB	0.0
FUEL PUMP	702801-5	002211	0.0
FUEL CONTROL UNIT	3244897-4	F66876	0.0
FLOW DIVIDER	25536-4	21307	0.0
OIL/FUEL HEATER	10552E	WA40133	0.0
COMP. BLEED VALVE	540-1407-4	GA1486	0.0

Key: TBA = To be assigned, N/A = Not Applicable Serial numbers are subject to change.

Comments: All engines ship FOB ATS dock.