



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-21	TSN:	7,227.4	TSO:	3,611.5	W/O#:	TBA
PCE:	25199	CSN:	7,320	CSO:	2,445	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	8F556	7,320	11,680
Disk, 2 nd Stg.	3013712	9N141	7,320	16,680
Disk, 3 rd Stg.	3011713	9N729	7,320	17,680
Impeller	3013176	2C214	7,320	11,680
Disk, CT	3013411	2P835	7,320	8,680
PT Disk, 1 st Stg.	3022412	8N295	7,320	12,680
Key: TBA = To be assigned, N/A = Not Applicable				

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-025G	1749913	3,611.5
FUEL PUMP	025323-101-03	12723	3,611.5
FUEL CONTROL UNIT	3244745-2	A75606	3,611.5
FLOW DIVIDER	25536	14132	3,611.5
OIL/FUEL HEATER	10522E	2457	3,611.5
COMP. BLEED VALVE	3100829-03	3H237	3,611.5
Key: TBA = To be assigned, N/A = Not Applicable			

Comments: All engines ship FOB ATS dock.