



**Airforce Turbine Service**  
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368  
 P.O. Box 146 Tynan, TX 78391  
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

<b>Engine Rotor Sheet</b>							
PT6A:	<b>-135</b>	TSN:	<b>3,388.1</b>	TSO:	<b>NA</b>	W/O#:	<b>10655</b>
PCE:	<b>92023</b>	CSN:	<b>3,899</b>	CSO:	<b>NA</b>	TSHS:	<b>1,255.0</b>

<b>Life Limited Part (LLP) Listing</b>				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 <sup>st</sup> Stg.	3013111	4A722	3,899	15,101
Disk, 2 <sup>nd</sup> Stg.	3013712	4A881	3,899	20,101
Disk, 3 <sup>rd</sup> Stg.	3011713	5A357	3,899	21,101
Impeller	3013176	1A873	3,899	15,101
Disk, CT	3024211	5A442	3,899	12,101
PT Disk, 1 <sup>st</sup> Stg.	3022312	6A215	3,899	26,101

Key: TBA = To be assigned, N/A = Not Applicable

<b>Accessories</b>			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-003	1482278	UNKNOWN
FUEL PUMP	025323-101	6217	UNKNOWN
FUEL CONTROL UNIT	3244777-4-3-2	A7048	UNKNOWN
FLOW DIVIDER	3014703	ATS577	UNKNOWN
OIL/FUEL HEATER	10552D	WA2595	UNKNOWN
COMP. BLEED VALVE	3105435-01	5Y045	UNKNOWN

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.