



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-114A	TSN:	16,595	TSO:	0.0	W/O#:	TBA
PCE:	PC0863	CSN:	33,347	CSO:	0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	TBD	14,851	4,149
Disk, 2 nd Stg.	3013712	56B613	18,476	5,524
Disk, 3 rd Stg.	3011713	56B958	18,476	6,524
Impeller	3027798	TXA1C1354	14,382	4,618
Disk, CT	3013411	A00014MK	12,655	3,345
PT Disk, 1 st Stg.	3026812	A0001XK5	13,951	6,049

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROP GOVERNOR	8210-002-01	1754940	0.0
FUEL PUMP	702801-5	001666	0.0
FUEL CONTROL UNIT	3244897-4-2	B10708	0.0
FLOW DIVIDER/START CONTROL	25536-4	20519	0.0
OIL/FUEL HEATER	10552E	4180	0.0
COMP. BLEED VALVE	540-1407-4	4507	0.0

Key: TBA = To be assigned, N/A = Not Applicable Serial numbers are subject to change.

Comments: All engines ship FOB ATS dock.